

RENEW ^{16/15} 21/22 T 285 R 5W

FUND - 2" IRON PIPE OR SHAFT
AT CORNER AND UNDER OLD F W
FENCE. ALSO FIND ORIG. 10' NW
20" W. OAK PARTLY ROTTED STUMP,
N 1/2° W 308' 9". GOOD SCRIBING VISIBLE
5' BT. NO OTHER BTS. FD.

NOTE - EVIDENCE OF OLD FENCE
TO SOUTH FROM COR. PIPE


I DO NOT SET BRASS CAP AT COR.

NEW BTS

7" W.O. BEARS N 63 1/2° E 469'
SCRIBED 5 15 T 285 R 5W CS BT

14" W.O. BEARS N 77° W 1192'
SCRIBED 5 16 T 285 R 5W CS BT

12" R. FIR BEARS S 81° W 1791'
SCRIBED 5 21 T 285 R 5W CS BT

NO TREES NEAR TO SE. 

RENEW 1/4 COR ¹⁵ T 285 R 5W
₂₂

FUND - SCRIBED POST OUT OF GROUND
NEAR COR. ALSO BOTH ORIG. BTS & BTS
AS RECORDED BY BBI - 1939 - THE ORIG
10" NW 24" W. OAK SHOWS GOOD SCAR I DO
NOT OPEN THE ORIG. 30" NW 45" LAUREL
CENTER ROTTED. BBI 8" NW 12" W. OAK
DOWN SCRIBING VISIBLE S 45° W 386. 8" W. OAK
NW 12" N 68° E 778' SHOWS GOOD SCAR I DO
NOT OPEN.

SET BRASS CAP AT COR. JAKD. ¹⁵
T 285 R 5W COUNTY SURVEYORS OFFICE ₂₂

NEW BTS

9" R. FIR BEARS N 49° W 150'
SCRIBED 1/4 S 15 CS BT

7" W. OAK BEARS S 30° W 422'
SCRIBED 1/4 S 22 CS BT

6/1996 VAR 20 1/2° J.B. C. FILE NO. 6758
M.G. S.B. 19/6/48

DIETZGEN NO. 388-6