

RENEW  $\frac{1011}{15 \ 14}$  T295 R5W

FOUND -- 1" X 4" 1" I.P. AT COR.  
STUMPS THAT CHECK 1921  
RENEWAL FOR NE & NW B.T.S. WE  
FIND STUMP HOLE THAT CHECKS  
SW BT. WE ALSO FIND NOW 12"  
R. FIR DOWN 56 1/4° E 13.2 WE OPEN  
& FIND GOOD SCRIBING "1/4"

SET BRASS CAP ALONGSIDE 1" I.P.  
AT COR. & MARK COUNTY SURVEYORS  
OFFICE 1961.  $\frac{510 \ 511}{515 \ 519}$  T295 R5W

NEW B.T.S.  
20" R. FIR BEARS N 11° W 108.5  
SCRIBED S 10 T 295 R 5W CS BT

15" R. FIR BEARS N 69° E 251.2  
SCRIBED S 11 T 293 R 5W CS BT

NO SUITABLE NEAR TO SOUTH

VAN LON  
DEC 5-1961  
J. B.  
D. M.  
J. P.

FILED  
RECEIVED

DEC 5 1961

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No. 99/A-17

DIETZGEN NO. 385-5

\*10/