

RENEW $\frac{1}{4}$ COR. 35 | 36 T 285 R 5W

FOUND - ORIG. 5" NOW 16" B. OAK
N 75° W 148.5' PREVIOUSLY
OPENED SHOWS GOOD SCRIBING
"BT" MARK TO NE NOT FOUND.

NOTE - COMPASS NEEDLE AT
CORNER SEEMS TO BE ABOUT
5 IN. ERROR, BUT OK AT BT.
BEARINGS TO NEW BTS ARE
AS READ AT CORNER.

SET BRASS CAP AT CORNER
MAD COUNTY SURVEYORS OFFICE
1961 $\frac{1}{4}$ S 35 S 36 T 285 R 5W

NEW BTS.

9" R. FIR BEARS S 54° W 105.7
SCRIBED $\frac{1}{4}$ S 35 CS BT

30" R. FIR BEARS N 23 $\frac{1}{2}$ ° E 64.0
SCRIBED $\frac{1}{4}$ S 36 CS BT
THIS BT $\frac{1}{4}$ IS AT FENCE COR.

VARLOZ

DEC 4 - 1961
J. B.
D. R.
J. P.

FILED

RECEIVED

DEC 4 1961

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

+ * O ✓

C. S. File No. 49/64-50

DIETZGEN NO. 385-6