

RENEW  $\frac{1}{4}$  COR 4/3 T 29 S R 5 W

FOUND BOTH OF MARKHAM'S BTS  
9" NW 10" CEDAR STUMP OUT OF  
GROUND SHOWS FACE & I BELIEVE  
A SCRIBE MARK IT HAS BEEN  
BADLY BURNED, STUMP HOLE CHECKS  
S 85° E 60° - THE NW BT DOWN  
& BADLY BURNED CHECKS OK.

WE ALSO FND  $\frac{3}{4}$ " I.P. AT COR

JET BRASS CAP ALONGSIDE I.P. &  
MARK COUNTY SURVEYORS OFFICE  
1961  $\frac{1}{4}$  S 4 1/3 T 29 S R 5 W,

NEW BTS.

22" R FIR BEARS S 64° W 40°  
SCRIBED  $\frac{1}{4}$  S 4 1/3 T 29 S R 5 W.

21" CEDAR BEARS N 20° E 143°  
SCRIBED  $\frac{1}{4}$  S 4 1/3 T 29 S R 5 W.

DEC. 19-1961  
U. B.  
J. M.  
U. P.

FILED  
RECEIVED

DEC 19 1961

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

\* \* O

Confidential 49/61-55

DIETZGEN NO. 385-6