

RENEW $\frac{16}{21}$ T 295 R 5W

FOUND - 3 1/2" P. AT ROR 6'
11" x 19" R. FIR N 78° W 30"
FACE OPENED PITCHED OVER
12" NOW 24" FIR STUMP 56" E 310"
SHOWS SCAR 12" NOW 16" PINE
S 55° W 495" OPENED CENTER
ROTTED & BURNED SHOWS FAULT
SCRIBING

SET BRASS CAP ALONGSIDE CAR.
PIPE & MARK COUNTY SURVEYORS
OFFICE 1967. ~~MARK~~ T 295 R 5W
R 1522

NEW BTS.
RESURVEY NOW 19" R. FIR N 78° W
316' C S BT

30" DOUBLE R. FIR N 30° E 8.9'
SCRIBED S 15 T 295 R 5W C S BT

16" R. FIR BEARS S 59 1/2° W 50 E
SCRIBED S 21 T 295 R 5W C S BT

15" R. FIR BEARS S 28° E 112.0
SCRIBED S 22 T 295 R 5W C S BT

VAR 20 1/2

MARCH 27-62
E.B.
D.M.
J.P.

DIETZEN NO. 388-6

* * ✓ ○

C.S. File No. 19/64-17