

RENEW ¹⁹²⁰_{30/29} T 285 R 4 W

FOUND - ORIG. 24" Now DOWN

↳ MOSTLY ROTTED PINE N 35° E

7 1/3' SHOWS GOOD SCRIBING ON

SECTION "520" WE ALSO FIND

1/2" I.R. AT COR AND ALL BTS.

AS RECORDED (ESLINGER 1951)

WE OPEN HIS NW BT AND FIND

NO SCRIBING SMALL BLAZE ONLY

ALL OTHER BTS SHOW SAME SMALL

SCAR I DO NOT BELIEVE HE SCRIBED

ANY BT. I ALSO BELIEVE TREE COR.

POSITION SHOULD BE N 35° E 8.5' FROM

ESLINGERS COR. FOR WE FIND OLD STUMP

HOLE, FENCE, AND STUMP SECT. THUS

OLD STUMP HOLE

8.5' BUT END OF TREE (DOWN HILL)

7 1/3'

8.5'

RECORD BASE OF OLD PINE NO SCRIBING FD.

SET BRASS CAP ALONG-SIDE 1/2" I.R. & MARK COUNTY SURVEYORS OFFICE 1961, 519/520 T 285 R 4 W 530/529

NEW BTS 7" R FIR BEARS N 10° E 270
SCRIBED 5 20 CS BT

39" CEDAR BEARS N 17 1/2° W 47°
SCRIBED T 285 R 4 W 5 19 CS BT

16" R. FIR BEARS S 80° W 23 1/2'
SCRIBED T 285 R 4 W 5 30 CS BT

15" CEDAR BEARS S 45° E 40'
SCRIBED T 285 R 4 W 5 29 CS BT

* + CS 49/67-27

1961/8