


RENEW SEC. COR. ¹⁸¹⁷
1920 T215 R4-W

FD 3/4" SHAFT AT FENCE COR. THIS
SET BY THEM 1920



ALSO FIND STUMP HOLE & PARTS OF
ROTTEN FIR THAT CHECKS BEARING
DUE TO ORIG. NEW BIT. I FIND BRASS SET
DID STUMP THAT CHECKS ORIG. S W BT.

I DO NOT SET BRASS CAP AT COR

NEW BITS.
6" R. FIR BEARS S 65° E 17 8'
SCRIBED S 20 T215 R4 W CS BT

10" R. FIR BEARS N 84° E 27 0'
SCRIBED S 17 T215 R4 W CS BT

18" DOUBLE LAUREL BEARS N 70° W 11 92'
SCRIBED S 18 T215 R4 W CS BT

NATURAL NEAR IN SW

J. W. B.
S. B.

3/1958

C.S. File No. 79/62-2

DIETZGEN NO. 385-6