

REM T 21 S R 4 W

COR. 29/28  
SECS. 32/33

AT COR. FD. OLD SCRIBED  
CEDAR STAKE - SO ROTTEN IT  
BROKE OFF WHEN TOUCHED,  
FD. FIR STUMP (NOW 36" DIAM.)  
S 7 1/2° W 15 3/4 FT. - OPENED & FD. SCRIBING  
"W" ON BADLY CHARRED FACE.

FD. FIR STUMP - (CUT LOW) N 45 1/2° W  
36 3/4 FT.

FD. ROTTED REMAINS OF FIR  
STUMP N 67° E 68° FT

FD. ROTTED FIR SNAG S 71° E  
128° FT. - NO MKS. LEFT.

AT COR. SET IRON PIPE WITH  
BRASS CAP MKD. "COUNTY SURVEYOR'S  
OFFICE 1964 T 21 S R 4 W S 29/328"  
S 32/533

BLAZE & SCRIBE NEW TREES:

14" DOUG. FIR S 55° E 23 5/8 FT.  
MKD. "T 21 S R 4 W S 33 CS BT"

10" DOUG. FIR N 85° E 33 7/8 FT.  
MKD. "T 21 S R 4 W S 28 CS BT"

11" DOUG. FIR N 7 1/2° W 115° FT.  
MKD. "T 21 S R 4 W S 29 CS BT"

NO GOOD TREES NEAR TO S.W.  
COR. IS IN FENCE COR. (FENCES  
NORTH & EAST) AND IN E. EDGE OF  
LOGGING ROAD.

SEE REM. # 38

OCT. 22, 1964

M.G.  
W.S.

Milo E. Coffey

M.S. 49/61-5

U. S. GEO. SURV.

#72  
+XV