

REN. T's 214 22 S R 5 W $\frac{S33}{S4} / \frac{S34}{S3}$

AT CDR. FD. 1" ALUMINUM PIPE

SET BY CALDER IN 1960.

FD. STUMP OF 24" DOUG. FIR N40°W
104² FT. - SCRIBING STILL VISIBLE "BT"
(THIS TREE MKD. IN REN. #3)

FD. ROTTEN FIR STUMP S15°E 169² FT.
NO MKS. VISIBLE - (ORIG. B.T.)

FD. STUMP OF 8" ALDER S30°E 244² FT.
(FACES VISIBLE BUT SCRIBING ROTTED AWAY.
(THIS TREE MKD. IN REN. #3)

FD. STUMP OF 4" INCENSE CEDAR
S37°E 36⁸ FT. - (CALDER'S B.T.)

FD. 8" DOUG. FIR S70°E 82² FT.
BLAZE & SCRIBE THIS FIR "T22SR5W S3CSBT"

FD. 8" DOUG. FIR S78°W 44² FT.
BLAZE & SCRIBE THIS FIR "T22SR5W S4CSBT"

BLAZE & SCRIBE 2 NEW TREES:

8" DOUG. FIR N86°E 57² FT.
MKD. "T21SR5W S34CSBT"

8" DOUG. FIR N54°W 34² FT.
MKD. "T21SR5W S33CSBT"

ALUM. PIPE EXTENDS APPROX 12"
ABOVE GROUND. - DID NOT SET BRASS CAP.

SEE RENS.

#62 & #3 T21SR5W

NOV. 30, 1964

MIG.

REN. #70 T22SR5W

M.S.

Milo E. Holroy

C.S. File No. 49/68-46