

REN.

T 21 S R 5 W

COR.

SECS.

27/26

34/35

AT COR. FD. OLD SCRIBED CEDAR  
STAKE - ROTTED OFF AT GROUND -  
+ 3/4" IRON ROD.

FD. BADLY ROTTED, OLD, UPROOTED  
FIR N 33° E 15<sup>0</sup> FT. - ON UNDER SIDE  
FD. BARK WITH FLATTENED AREA SHOW-  
ING FRAGMENTARY BARK SCRIBING.

FD. CEDAR STUMP S 69° W 37<sup>0</sup> FT.  
SHOWING EVIDENCE OF UPPER &  
LOWER FACES, BUT NO SCRIBING. -  
FACES BADLY ROTTED.

NO TRACE FD. OF ORIG S.E. OR  
N.W. B.T.'S.

FD. 15" MAPLE S 73° E 11<sup>0</sup> FT. -  
SCRIBING VISIBLE "21 R 5 S 35 CS BT"

FD. 27" MAPLE N 34° W 32<sup>0</sup> FT. -  
SCRIBING VISIBLE "T 21 S R 5 W S 27 CS"  
(NO RECORD OF RENEWAL FOUND)

DID NOT SET BRASS CAP.

BLAZE & SCRIBE 2 NEW TREES:

6" DOUG. FIR N 81° E 4<sup>5</sup> FT.  
MKD. "T 21 S R 5 W S 26 CS BT"

13" INCENSE CEDAR S 51° W 23<sup>2</sup> FT.  
MKD. "T 21 S R 5 W S 34 CS BT"

DEC. 3, 1964

Milo E. Godfrey

M. G.

W. S.

M. S.

○  
3106  
+ X ✓

C. S. File No.

42/68-90