

32133 T 245 R 3 W
RENEW 5/4 T 255

FOUND - SCRIBED STAKE & STEEL FENCE POST AT COR. I ALSO FIND BRASS CAP OUT OF POSITION & COVERED BY DOWN-FALL. I RESET BRASS CAP AT COR. & SCRIBE NEW BTS. ALL EXISTING BTS ARE NOW DOWNFALLS. ALL CHECK RECORD.

NEW BTS.

1 1/2" W. FIR BEARS N 45° E 19.7'
SCRIBED 532 T 255 R 3 W C S BT

1 1/2" CEDAR BEARS S 61° E 30.3'
SCRIBED 532 T 255 R 3 W C S BT

7" W. FIR BEARS S 26° W 6P
SCRIBED 532 T 255 R 3 W C S BT

5" CEDAR BEARS N 36° W 27.5'
SCRIBED 532 C S BT

RENEW 1/4 COR. 3/2 T 255 R 3 W

FO - BRASS CAP AT COR. & NW BT (NOW DOWNFALL) SHOWS GOOD SCRIBING "B" NE BT GONE

NEW BTS.

NOTE - NO TREES NEAR

6 1/2" FIR STUMP BEARS N 74° W 35.3'
SCRIBED 1/4 S 3 C S BT

6" FIR STUMP S 68° E 134.0'
SCRIBED 1/4 S 2 C S BT

VAR. 20 1/2

MARCH 24 - 60

J. B.
M. G.
C. P.

DIETZGEN NO. 3885