

T 27 S R 6 W

COR. SECS.

20	21
29	28

AT COR. FD. $\frac{3}{4}$ " GALV. IRON PIPE SET BY STEWART IN H22 IN GOOD CONDITION.

FD. ALL OF STEWART'S B.T.S AS FOLLOWS:

8" W. OAK (NOW 14" DIAM.) N 45° E 50 FT. IN GOOD CONDITION. SHOWS GOOD SCAR.

24" W. OAK (NOW 24" DIAM.) S 67° E 98 FT. (ORIG. B.T.) NEARLY DEAD - FACE ROTTED OUT,

18" W. OAK (NOW 18" DIAM.) N 30° W 67 $\frac{1}{2}$ FT. TREE APPEARS TO BE DYING. SHOWS GOOD SCAR.

18" W. OAK S 37 $\frac{3}{4}$ ° W 88 $\frac{1}{2}$ FT. DEAD & PARTLY ROTTEN. (ORIG. B.T.)

FD. ROTTED STUMPS IN PLACE OF THE ORIG. N.W. & N.E. B.T.S. CHECK BEARING & DIST.

BLAZE & SCRIBE 3 NEW TREES AS FOLLOWS:

6" W. OAK N 36° W 7 $\frac{1}{2}$ FT. MKD.
"T 27 S R 6 W S 20 CS BT."

9" W. OAK S 75 $\frac{1}{2}$ ° W 17 $\frac{1}{2}$ FT. MKD.
"T 27 S R 6 W S 29 CS BT"

11" W. OAK S 11° E 22 $\frac{1}{2}$ FT. MKD.
"T 27 S R 6 W S 28 CS BT"

DID NOT SET BRASS CAP,

JAN. 11, 1961

J. B.

M. G.

C. P.

Milo E. Godfrey

*
C. S. File No.

49/79-7