

RENEW 33/34 T275 R7W

AP 12

FOUND - STUMP (NOW 18") N63° E  
2LP SHOWS OLD SCARS AND BURNED  
AREAS. NO SCRIBING FOUND. WE ALSO  
FIND AP WHICH BEARS N32° E 90.4'  
CHECKS DIST. & BEARING. WE DO NOT  
FIND NW BT

WE FIND BRASS CAP (1924 SURVEY)  
LAYING ON STUMP NEAR COR.

RESET BRASS CAP. AT COR.  
AND 15' WEST OF NEW WIRE FENCE

NEW BTS.

8" R. FIR BEARS N 60<sup>3</sup>/<sub>4</sub>° W 74' 0"  
SCRIBED T275 R7W 533 CS BT

9" R. FIR BEARS N 60° E 102'  
SCRIBED T275 R7W 534 CS BT



DIETZEN NO. 385-6

RENEW AP WHICH BEARS N32° E  
90.4' FROM SEC COR 33/34

FOUND - BRASS CAP AT COR.  
N2

NEW BTS.

12" LAUREL BEARS S 71° E 63'  
SCRIBED AP CS BT

12" WHITE FIR BEARS N 29° W 413'  
SCRIBED AP CS BT

FEB. 9 - 1961

VAR 20 H°

J. B.  
N. G.  
C. D.

WV

C. S. File No. 49/79-23