

RENEW $\frac{1}{4}$ COR 30 | 29 T27S R27W

FOUND - ORIG. 10" NEW 14" W.O. I
OPEN OLD SQR AND FIND GOOD SCRIBING
"BT" THIS BT STILL PARTLY ALIVE.
THE ORIG. NW BT GONE.

SET BRASS CAP AT COR. MKD. $\frac{1}{4}$ S 30 52
T27S R27W COUNTY SURVEYORS
OFFICE 1958
N S FENCE LINE IS EXACT 90'

NEW BTS.
14" P. FIR BEARS N 45° E 64.2'
SCRIBED $\frac{1}{4}$ S 29 C S BT

18" B.O. BEARS S 32° E 33.4'
SCRIBED $\frac{1}{4}$ S 29 C S BT

RENEW NW COR DUC 53 T27S R27W
FOUND -

BT AS RECORDED BY RICHARDSON
1929 10" FIR 34.3" E 15.2" OPEN FACE
GOOD SCRIBING CL 53 C S BT THIS BT
NOW SNAG PARTLY ROTTED

SET BRASS CAP AT COR. MKD.
NW COR. CL 53 - 27S R27W
COUNTY SURVEYORS OFFICE 1958
N S FENCE LINE THROUGH COR.

NEW BTS.

6" CEDAR BEARS S 64° E 31.5'
SCRIBED NW CL 53 C S BT

17" CEDAR BEARS N 13° E 36.2'
SCRIBED NW CL 53 C S BT

C.S. No. 10119-51

4/1958

DIETZGEN NO. 3885-6