

REVIEW SEC. COR. $\frac{5}{8}$ T 24S R6W

FOUND - ORIG. 20" NOW 24" R. FIR
SIPING 37.9' OPEN FACE GOOD SCRIBING
BT (NOW DEAD) ORIG 4" NOW 12"
CEDAR SNAG N 26° W 9.9' I OPEN F. FIND
SCRIBED MARKS I ALSO FIND 4.9" FIR
STUMP THAT CHECKS RECORD DIST. & BEARING
FOR THE ORIG. BT. I DO NOT OPEN

SET BRASS CAP AT CORNER
MKD $\frac{5}{8}$ T 24S R6W
58 59 COUNTY SURVEYORS OFFICE 1958

NEW BTS.

24" WHITE FIR BEARS N 70° W 118.5'
SCRIBED $\frac{5}{8}$ T 24S R6W CORN

12" R. FIR BEARS S 44° W 110.5'
SCRIBED $\frac{5}{8}$ T 24S R6W CORN

38" CEDAR BEARS N 35° E 180.0'
SCRIBED $\frac{5}{8}$ T 24S R6W CORN

NO TREES NEAR IN SE

REVIEW SEC. COR. $\frac{5}{4}$ T 24S R6W

FOUND - ORIG. 7" NOW DEAD 10" FIR
SIPING 50' OPEN FACE GOOD SCRIBING
BT. I ALSO FD NOW 22" R. FIR
HAS OPEN FACE BUT BADLY BURNED NO
SCRIBING FD.

SET BRASS CAP AT CORNER MKD.

$\frac{5}{4}$ COR. 5509 T 24S R6W.
COUNTY SURVEYORS OFFICE 1958.

NEW BTS.

28" R. FIR BEARS S 24° W 160
SCRIBED $\frac{5}{4}$ T 24S R6W CORN

24" R. FIR BEARS N 67° E 99.0'
SCRIBED $\frac{5}{4}$ T 24S R6W CORN

M. B. L. 198
M. B.
S. B.

C. S. File No. 49/83

DIETZEN NO. 385-6