

RENEW $\frac{1}{4}$ COR 23/24 T24S R8W

FOUND - BOTH OLD B.T.S. BOTH ANNEALS
IN GOOD CONDITION & BOTH CHECK
FOR BEARINGS & DISTANCES. I OPEN
THE NE BT & FIND GOOD SCRIBING "S"
I DO NOT OPEN THE SW BT SHOWS
GOOD SCAR.

SET BRASS CAP AT COR. MKD.
 $\frac{1}{4}$ S23/S24 T24S R8W. COUNTY
SURVEYORS OFFICE, 1958.

NEW B.T.S.

I RESCRIBE NOW 35" R. FIR N75 $\frac{1}{2}$ °E
66.7' $\frac{1}{4}$ S 24 CS BT
12" R. FIR S47 $\frac{1}{2}$ °W 40.2'
SCRIBED $\frac{1}{4}$ S 23 CS BT.

VAR. 20 $\frac{1}{2}$ ° MAY 1, 1958

J. B.

M. G.

S. B.

YAN

ROYEVILLE TOWN
SURVEYORS OFFICE

C. S. File No.

49/84-1