

Reset  $\frac{1}{4}$  510 & 511

T245 R2W

Reset BRASS cap removed for

Road construction from following

BTs - See Rem. # 38 & CS. 49/84

9" W. FIR N. 47° E. 30<sup>3</sup> ft.

Mkd. "  $\frac{1}{4}$  511 CS BT "

18" D. FIR N. 49° W. 26<sup>3</sup> ft.

Mkd. "  $\frac{1}{4}$  510 CS BT "

8" W. FIR N. 11° W. 61<sup>2</sup> ft.

Mkd. "  $\frac{1}{4}$  510 CS BT "

COR. Lies approx 40 ft.

West of approx center line of New

access Road & 20 ft. West of top

of cut bank - Road course N.E.

Oct. 19, 1966

U.R.T.B.

J.H.

D.W.

*U.R.T.B.*

FILED

RECEIVED

OCT 19 1966

COUNTY SURVEYOR

DOUGLAS COUNTY, ORE.



O.K. J.W.B.

C.S. File No.

49/84-23