

RENEW 1/4 COR 19 20 T 24S R 2W

FOUND - ORIG. 50" NOYV 58" FIR STUMP  
N 89° E 330' I OPEN LOWER SEAR &  
FIND GOOD SCRIBING "T" I ALSO FIND  
16" METAL STUB THAT CHECKS BEARING  
& DIST. FOR ORIG SW BT

SET BRASS CAP AT COR. MKD 1/4 S 19 320  
T 24S R 2W COUNTY SURVEYORS  
OFFICE 1958

NEW BTS  
12" CEDAR BEARS S 27 1/2° E 77 1/2'  
SCRIBED 1/4 S 20 CS BT

14" R FIR BEARS N 62° W 68'  
SCRIBED 1/4 S 19 CS BT

NOTE CEDAR BT SCRIBED HIGH  
TOP SCRIBED 8' ABOVE GR.

RENEW 1/4 35 T 24S R 8W

FOUND - BOTH ORIG. BTS, BOTH CHECK FOR  
BEARING & DIST. OR G. 24" NOYV 26"  
R FIR N 80° W 185' HAS GOOD BARK  
SCRIBING "X" 2". I DO NOT FIND SCRIBING  
ON SW BT CENTER ROTTED.

SET BRASS CAP AT COR. MKD 1/4 S 35  
T 24S R 8W COUNTY SURVEYORS  
OFFICE 1958 52

NEW BTS  
20" CEDAR BEARS S 70° W 380'  
SCRIBED 1/4 S 2 CS BT

36" R. FIR BEARS N 8° W 185'  
BARK SCRIBED 1/4 S 35 CS BT

VAR 20 1/2"  
N 14-55  
J.B.  
M.G.  
S.B.

DIETZGEN NO. 2 3855-6