

Renew $\frac{1}{4} \frac{53}{510}$ T255 R8W

Fd. O.B.T.'s as follows MKd. in 1911 survey -

20" BURNT FIR STUB S. 71° E. 4 $\frac{1}{2}$ ft.

Very Badly decayed - Blazed & very poor
scribe " $\frac{1}{4}$ U" visible.

20" BURNT FIR STUB N. 88° E. 10 $\frac{1}{2}$ ft.

Record. 103 $\frac{1}{2}$ ft. Badly decayed - No

scribe Fd. - Set 1" I.P. & BRASS CAP

Mkd. "COUNTY SURVEYOR'S OFFICE

1967 T255 $\frac{1}{4} \frac{53}{510}$ R8W" &

MK, New B.T.'s as follows -

16" D. FIR S. 27° E. 6 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 510 CS BT"

8" D. FIR N. 33° W. 6 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 53 CS BT"

This cor. Lies on very steep

North slope approx. 150 ft.

South of Little Wolf creek.

Sept 26, 1967

V.R.T.
J.H.

(Signature)

#58

O.K. J.W.B.

C.S. File No.

49/88-19