

REN. T21 S R5 5 & 6 W

12/7  
13/18

FD. CEDAR TREE (NOW 24" DIAM.)

N75°W 23<sup>1</sup>/<sub>2</sub> FT. SCRIBING VISIBLE ON  
BADLY BURNED & ROTTED OLD FACE "T2 S"

FD FIR STUMP (NOW 40" DIAM.) N47°E  
5<sup>3</sup>/<sub>2</sub> FT. NO SCRIBING FD. BUT OLD AXE  
MKS. GIVE APPEARANCE OF HAVING BEEN  
SMOOTHED OFF FOR BARK SCRIBING.

FD. FIR STUMP (NOW 34" DIAM.) S54°E  
9<sup>1</sup>/<sub>2</sub> FT. (INSTEAD OF 10<sup>6</sup>/<sub>8</sub> FT.) SCRIBING  
VISIBLE ON OLD FACE WHICH HAS BEEN  
PREVIOUSLY OPENED "S18 T21 S R5 W"  
NO TRACE FD. OF S.W. TREE,  
AT COR. SET IRON PIPE WITH BRASS CAP

MKD. "COUNTY SURVEYOR'S OFFICE 1961

T21 S <sup>9</sup>S12 | S7 R "  
6 S13 | S18 W

BLAZE & SCRIBE NEW TREES!

36" DOUGLAS FIR S65°W 30<sup>2</sup>/<sub>2</sub> FT. MKD.  
"T21 SR6W S13 CS BT."

24" DOUGLAS FIR WEST 42<sup>2</sup>/<sub>2</sub> FT. MKD.  
"T21 SR6W S12 CS BT"

16" DOUGLAS FIR S19°E 47<sup>1</sup>/<sub>2</sub> FT. MKD.  
"T21 S R5W S18 CS BT"

NO TREES AVAILABLE IN N.E. QUADRANT  
DEC. 19, 1961

*Paul E. Colby* C.S. File No. 716