

REN.

T 20 S R 7 W

E 1/4 S 25

FD. HAINES "T" IRON & CAP AT  
COR. ALSO 1/2" GALV. IRON PIPE,

FD. OLD FIR STUMP S 83° W 29<sup>0</sup>  
FT. (INSTEAD OF 32<sup>3</sup> FT.) FD. GOOD  
SCRIBING - PART OF "4" & A "B"

FD. OLD FIR STUMP S 42° E 5<sup>3</sup> FT.  
OLD FACE BURNED AWAY. - HAD BEEN  
PREVIOUSLY OPENED.

DID NOT FIND SANDSTONE CALLED  
FOR IN OLD NOTES.

FD. 8" FIR S 67° E 30<sup>3</sup> FT. SCRIBED  
"1/4 SBT"

DOUBLE  
FD. 8" MAPLE EAST 18<sup>2</sup> FT.  
SCRIBED IN BARK "1/4 SBT"

DID NOT SET BRASS CAP.

BLAZED & SCRIBED ONE NEW TREE!

4" DOUGLAS FIR S 58° W 23<sup>3</sup> FT.  
MKP. "1/4 S 25 CS BT"

NO OTHER TREES AVAILABLE.

JAN. 18, 1902

Milo E. Godfrey

M.G.  
C.P.