

REN.

T 21 S R 5 W

COR. SECS.

21/22
28/27

AT COR. FD. 4" PIPE SET BY

THIEL. A BADLY BURNED STAKE ALONGSIDE OF PIPE, REMNANTS OF SCRIBING STILL VISIBLE.

FD. FIR STUMP N 63° W 11 8/10 FT.

GOOD SCRIBING VISIBLE "BT"

FD. FIR STUMP S 81° W 12 3/4 FT.

SHOWS GOOD SCAR.

FD. FIR STUMP N 79° E 23 1/2 FT.

SCAR NOT VERY NOTICEABLE.

FD. FIR STUMP S 24° E 42 3/4 FT.

SHOWS FAINT SCAR.

BADLY ROTTED STUMPS OF BRIG, N.W. & S.W. B.T.'S FD. NO SCARS OR SCRIBING VISIBLE NOW.

1/2" PIPE EXTENDS 14" ABOVE GROUND. NO NEW MONUMENT SET.

BLAZE & SCRIBE NEW TREES:

15" CHINQUAPIN S 31° E 126 8/10 FT.

MKD. "T 21 S R 5 W S 27 CS BT"

9" DOUG. FIR N 18° E 98 1/2 FT

MKD. "T 21 S R 5 W S 22 CS BT"

NO LIVE TREES AVAILABLE WEST OF LINE.

DROVE 3/4" IRON ROD WEST 89 3/4 FT.

FROM COR. IN N.E.S. FENCE LINE ON WEST SIDE OF CHURCHILL ROAD.

APR. 11, 1962
M.G.

+* ✓ Milo E. Godfrey C.S. File No. 49/89-53