

RENEW  $\frac{1}{4}$  CAP 10/11 T 325 R 6 W

FOUND - BOTH H ORIG. BTS. ORIG 18"

NOW 24" FIR PARTLY ROTTED SNAG

S 70° E 106' SHOWS GOOD SCRIBING

" $\frac{1}{4}$ " S " ORIG. 48" NEW 50"

FIR STUMP N 10° W 205' I DO NOT

FIND ANY SCRIBING MAY HAVE BEEN

BARK SCRIBED. I ALSO FIND  $\frac{3}{4}$ "

IRON PIPE AT CORNER.

SET BRASS CAP AT CORNER MKD.

COUNTY SURVEYORS OFFICE 1959

$\frac{1}{4}$  S 10/S 11 T 325 R 6 W

NEW BTS.

16" CEDAR BEARS S 53° E 380'

SCRIBED  $\frac{1}{4}$  S 11 CS BT

12" R. FIR BEARS S 85° W 276'

SCRIBED  $\frac{1}{4}$  S 10 CS BT.

\*

6/1959

CS 49/91-5 ✓