

RENEW $\frac{1}{4}$ COR. 23/29 T 205 R7W

FOUND - STONE AT COR. & MARKED AS RECORDED. I ALSO FIND BOTH ORIG. BIT. ORIG. 27" NOW 32" BURNED & PARTLY ROTTED FIR SNAG. N 66° E 19.8' SHOULD BE N 60° E 16.8'. ORIG. 18" NOW 20" BURNED & PARTLY ROTTED FIR SNAG. SHOULD BE 13.8'. I FIND NO SCRIBING ON EITHER. BITERY MAY HAVE BEEN REWRITTEN. I DO NOT SEE BRASS CAP AT COR.

NEW BIT.

32" R. FIR N 65° W 64'
SCRIBED $\frac{1}{4}$ S 23 CSBT

15" R. FIR N 61° E 50.6'
SCRIBED $\frac{1}{4}$ S 2 CSBT

VAR 20 ±' NW

NOV. 3 - 58
J.B.
M.G.
S.B.

DIETZEN NO. 385-6

RENEW $\frac{23}{29}$ T 205 R 7W

FOUND - (IRON & 1" CAP) AT COR. ORIG. 14" NOW 36" FIR STUMP RECORD N 18° E 11.9' SHOULD BE N 2° E 11.9'. I OPEN & FIND GOOD SCRIBING 524" ORIG. 14" NOW 31" FIR RECORD NOW 132" SHOULD BE N 18° W 13.2'. ORIG. 10" NOW 24" R. FIR S 20° W 17.8' SHOWS GOOD SCAR. I DO NOT OPEN.

I DO NOT SEE BRASS CAP AT COR.

NEW BIT

26" R. FIR BEARS S 38° E 17.5'
SCRIBED S 25 T 20 S R 7W CSBT.

11/1958

C. S. File No. 49/93-5