

RENEW $\frac{116}{127}$ T 29 S

R9W R8W

FOUND - ORIG. 18" NOW 40" R. FIR

N 75° E. 33' SHOWS OLD BARK SCRIBING

"T 29 S" ALSO SHOWS NEWER SCRIBING

ORIG. 12" NOW 30" FIR STUMP

S 67° W 40.2' SHOWS OLD BARK

SCRIBING "T 29 S R 9 W" ALSO SHOWS

NEWER BARK SCRIBING. I ALSO FIND

STUMP HOLE THAT CHECKS BEARING

& DIST. FOR SE BT. I FIND NO TRACE

OF NW BT. I FIND 3" X 6" X 12"

SANDSTONE AT COR.

SET BRASS CAP AT CORNER MKD

COUNTY SURVEYORS OFFICE 1958

51/56 T 29 S

512/57
R9W R8W

NEW BTS. -

12" R. FIR BEARS N 42° W 59.2

SCRIBED 51 T 29 S R 9 W C 5 BT

16" R. FIR BEARS S 59½° W 44.5'

SCRIBED 512 T 29 S R 9 W C 5 BT.

RE BARK. SCRIBE 40" R. FIR N 75° E

4.2' 56 T 29 S R 8 W C 5 BT.

14" R. FIR BEARS S 28° E 42.7'

✓ SCRIBED 57 T 29 S R 8 W C 3 BT.

9/1958

CS 49/100-10