

22 23

N 55° W 50'

RENEW 22 23

T 295 R 8W

FOUND - ORIG. 20" NOW 26" ROTTED  
 SNAG 347°E 210' - OPEN NEAR BASE  
 I FIND GOOD SCRIBING "BT" ORIG.  
 30" NOW 40" FIR STUMP S 89° W 330'  
 SHOWS GOOD SCAR, I DO NOT OPEN I  
 FIND NO TRACE OF OTHER ORIG. B.T.S.

SET BRASS CAP AT CORNER MKD  
 COUNTY SURVEYORS OFFICE 1958  
 S 22 5 23 T 295 R 8W  
 527 5 26

NEW B.T.S.

10" R. FIR BEARS S 24 1/2° E 26.5'  
 SCRIBED S 26 T 295 R 8W C.S. BT

6" R. FIR BEARS N 20° E 40'  
 SCRIBED S 23 C.S. BT

6" CHINAQUIN BEARS NORTH 28°  
 SCRIBED S 22 T 295 R 8W C.S. BT

9" CHINAQUIN BEARS S 65° W 190'  
 SCRIBED S 27 T 295 R 8W C.S. BT.

YAR 20 5 20

OCT 10 - 58  
 J.B.  
 M.G.  
 S.B.

RENEW 22 23

T 295 R 8W

FOUND - ORIG. 40" NOW 58' DOWN FIR  
 I OPEN OLD SCAR & FIND GOOD  
 SCRIBING "B" I FIND NO TRACE  
 OF ORIG. N.E. BT.

SET BRASS CAP AT CORNER MKD  
 S 23 T 295 R 8W COUNTY  
 S 26 SURVEYORS OFFICE 1958

NEW B.T.S.

30" R. FIR BEARS S 31° W 175'  
 SCRIBED S 26 C.S. BT

1" CEDAR BEARS N 29° E 39.7'  
 SCRIBED S 23 C.S. BT

NOTE - CORNER UNDER 4' DOWN  
 FIR.

C.S. File No. 49/100-40

DIETZEN NO. 385-6