

RENEW $\frac{1}{4}$ COR. 17/16 T 29 S. R 6 W

FUND - ORIG. 30" NOW 18" W OAK
N 85° E 79.9' I OPEN & FIND GOOD SCRIBE
MKS "BT". I FIND NO TRACE OF OAK.
S W BT, I ALSO FIND 16" X 16" X 8"
STONE AT CORNER

SET BRASS CAP AT CORNER MND
 $\frac{1}{4}$ S 17/16 T 29 S R 6 W COUNTY
SURVEYORS OFFICE 1958

NEW B.TS.

(DOUBLE)

14" CEDAR BEARS N 18° E 30.6
SCRIBED $\frac{1}{4}$ S 16 CS BT,

8 CEDAR BEARS S 77° W 70.1
SCRIBED $\frac{1}{4}$ S 17 CS BT

ANCHOR POST BEARS N 85° W 10.5
POSTS TO NORTH

RENEW $\frac{1}{4}$ COR. S T 29 S R 6 W

FUND - 3" X 10" ~~OAK~~ BRAKE LEVER

ARM AT COR. & BOTH B.TS. AS
RECORDED BY B.R.I. 18" NOW 28"
FIR STUMP S 76 $\frac{1}{2}$ ° W 41.5' I OPEN
& FIND GOOD SCRIBING "BT".

22" NOW 16" FIR SHOWS GOOD SCRIBE.
I DO NOT OPEN N 48° E 22.7'
I ALSO FIND "H 20" ON 10" X 10" X 4"
BEARS N 15° E 13.3' STONE

SET BRASS CAP AT COR. & ALONGSIDE
LEVER MND CAP $\frac{1}{4}$ S 9 T 29 S R 6 W
COUNTY SURVEYORS OFFICE 1958

NEW BT

28" R FIR BEARS S 34 $\frac{1}{2}$ ° E 21.6
SCRIBED $\frac{1}{4}$ S 16 CS BT

DIETZEN NO. 385-6

10/1958

C. S. File No.

49/100

46