

RENEW  $\frac{1}{4}$  COR 23 T29S R9W  
R6

FOUND 1" SQ. SHAFT AT COR. &  
2" FIR STUMP S  $3\frac{1}{4}$  W 61.5' NO  
SCRIBING FOR STUMP CUT LOW. I ALSO  
FIND ROOT SYSTEM OF LARGE FIR  
THAT CHECKS BEARING & DIST FOR  
NW BT

I DO NOT SEE BRASS CAP AT COR.

NEW BTD.  
2" FIR BEARS S  $29\frac{1}{2}$  W 147.0'  
SCRIBED  $\frac{1}{4}$  S 26 C S BT

7" FIR BEARS N  $27^{\circ}$  W 112.5'  
SCRIBED  $\frac{1}{4}$  S 23 C S BT

DIETZBEEN D. 3955-B

FILED  
RECEIVED

SEPT 25-59  
J.B.  
M.G.  
G.P.

SEP 25 1959

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

\*

✓ ✓ C. S. File No. 49/100 520