

REVIEW 1/4 COR. 15/14 T305 R9W

FOUND - BASE SECTION OF  
DOWN & DOTTED FIR SHOWS  
GOOD SCRIBING "B-1" ON OLD FACE  
WE ALSO FIND DOWN CEDAR TO NE  
SET BRASS CAP AT CORNER MAD.  
COUNTY SURVEYORS OFFICE, 1463 1/4 S 15TH  
T305 R9W

NEW BTS.

7" FIR BEARD S 25' E 118'  
SCRIBED 1/4 SECTION BT

5" FIR BEARD S 52' W 39'  
SCRIBED 1/4 SECTION BT


MAY 10 - 68  
M. D.  
B. S.

DIETZGEN NO. 388-6

C. S. File No. 49/100-88

Section 14 Twp 30S Rge 9 N

Date: July 2, 1963



AS 42/100-80

How was corner identified? 'BT' SCRIBE ON ROTTEN STUBS

Condition of corner: Very Poor

Best route to reach corner: OLD C&D. ROAD OVER OLD BRIDGE

Tag on old land 300' North of cor.

Quadrant	NB	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
<u>Original</u> or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks:

-63

Blank & Houshka

RSARE. Signed LUMBER