

Review $\frac{1}{4}$ 523 & 524 T255 R2W

Fd. Cad. BRASS cap & $\frac{1}{2}$ " I.P. 2 long side
in mound of Stone MKd. $\frac{1}{4}$ 523/524

T255 R2W 1962 " & BT's as follows -

ORIG. 66" FIR N. 69° E. 11 1/2 ft.

Shows good SCOR - we do not open

ORIG. 30" FIR N. 37° W. 17 1/2 ft.

Badly rotted stump - shows "Y41" scribe.

BT Recorded in Ren. # 25 is Destroyed

I.P. also Recorded in above Ren. - New

Cad. BT To NW Destroyed. We MK.

New BT's -

12" Hemlock S. 48° E. 26 1/2 ft.

Mkd. " $\frac{1}{4}$ 524 CS BT "

7" Hemlock N. 57° W. 83 1/2 ft.

Mkd. " $\frac{1}{4}$ 523 CS BT "

April 27, 1966

U.R.T.
M.S.
J.H.

FILED

RECEIVED

APR 27 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Q 359

C.S. No. 59/102-13