

REN. T 22 S R 9 W  $\frac{1}{4}$  S17  
S20

REN. FROM MAPLE B.T. (NOW  
33" DIAM.) N 88° E 6 1/2 FT. DID NOT  
OPEN FOR SCRIBING - NEW GROWTH ON  
TREE ALL ON W. SIDE - DEAD ON E. SIDE -  
TREE WOULD HAVE BEEN DEMOLISHED.

AVAILABLE TREES FOR NEW BITS VERY  
SCARCE. LOCATION IDENTIFIED BY  
RUNNING EAST FROM COR. SECS. 18 1/2"  
AND FROM CALLS ON CREEKS EAST AND  
WEST OF 1/4 COR., WHICH I CHECKED CALLS  
IN ORIG. GOVT FIELD NOTES. TREE  
SHOWED SCAR ON SOUTH SIDE WHERE  
OTHER FORK OF TREE ORIGINALLY STOOD.

AT COR. SET IRON PIPE WITH  
BRASS CAP MKD. "COUNTY SURVEYOR'S  
OFFICE 1962 T 22 S R 9 W  $\frac{1}{4}$  S17"  
S20

- 3 1/2" DOUG. FIR NEW TREES:
- 16" HEMLOCK N 56° W 95 1/2 FT.
- MKD. "1/4 S 17 CS BT"
- 8" MAPLE N 88° E 4 1/2 FT. MKD.
- "1/4 S17 CS BT" (NEW FORK OF OLD B.T.)
- 3" DOUG. FIR S 12° E 18 1/2 FT.
- MKD. "1/4 BT" (NO OTHER TREES AVAILABLE  
SOUTH OF LINE)

JUNE 25, 1962

+ \* ✓

W. E. Godfrey CS. 49/103 M.S.  
SY. T.