

RENEW $\frac{57^f}{819}$ T32S R8W

FOUND - ORIG. 48" NOW 42" R. FIR
N65°E 14.5' I FIND GOOD BARK
SCRIBING "T32S". I ALSO FIND
NOW 24" R. FIR THAT CHECKS
BEARING & DIST FOR ORIG. NW BT.

NOTE - THIS COR. & ALL BTS.
ARE IN FILL SLOPE OF ROAD
I UNCOVER FILL MATERIAL TO FIND
SCRIBING.

I ALSO FIND 1" DRILL STEEL AT
COR. I DO NOT SET BRASS CAP.

NEW BTS. I DESCRIBE (BARK)
42" R. FIR N65°E 14.5' S9 T32S
R8W CS BT.

24" R. FIR N54°W 16.2'
SCRIBED S5 T32S R8W CS BT.

36" R. FIR N58°E 27.8'
SCRIBED S4 T32S R8W CS BT.

VAR. 20 $\frac{1}{2}$ ° J. B.

M. G.

S. B.

FILED

RECEIVED

AUG 12 1958

COUNTY SURVEYOR

DOUGLAS COUNTY, ORE.

C. S. File No.

49/100