


RENEW 1/4 COR. 8/9 T25S R6W

5265° W 35.5'

FOUND — GERMOND'S 90" OAK, NOW
STUMP GOOD SCRIBING "1/4 S" I ALSO FIND
18" OAK STUMP THAT CHECKS BEARING
DIST. FOR ORIG. SET BY (STUMP LOW CUT
NO SCRIBING FOUND). I DO NOT FIND
STONE SET BY GERMOND.

SET BRASS CAP AT CORNER, MND
COUNTY SURVEYORS OFFICE 1958
1/4 S 8/9 T25S R6W



NEW SETS

2" R FIR BEARS N 85° E 21.6
SCRIBED 1/4 S 8 CB BT

RIV OAK BEARS N 68 1/2° W 60.3'
SCRIBED 1/4 S 8 CB BT

✓ VAR 20 30

NOV 10-58

J.B.

M.S.

S.R.

RENEW 1/4 COR. 7/8 T25S R6W

FOUND GERMOND'S 50" FIR (NOW 61") N 60° W
17.8 FT. GOOD BLAZE — NO SCRIBING FOUND.

FOUND COMPLETELY ROTTED STUMP N 75° E
10.6 FT. PITCHED OVER BLIVER ARM FACE OF
THIS TREE SCRIBED "1/4 S 8 BT" WAS STUCK IN
KEDGE BESIDE REMNANT OF OLD STUMP.

FOUND PART OF OLD SQUARED OAK POST
(NO SCRIBING VISIBLE) LYING ON GROUND
ALONGSIDE OF COR.

AT COR. SET IRON NAIL WITH BRASS
CAP MND. "COUNTY SURVEYOR'S OFFICE 1958
T25S R6W 1/4 S 8 BT

BLAZE & SCRIBE 2 NEW TREES
18" DOUG. FIR N 81° E 10.2 FT. "1/4 S 8 CB BT"
11" DOUG. FIR N 80° W 32.8 FT. "1/4 S 7 CB BT"

✓ ✓ C. S. File No. 49/123