

REN Twps 25 & 26 S R6W  $\frac{1}{4}$   $\frac{S35}{S2}$

FD. FIR STUMP (NOW 46" DIAM.)

N 32° E 30 $\frac{1}{2}$  FT. - CUT OPEN & FD.  
ONE SCRIBE MK. "1" - TREE HAD  
BEEN OPENED PREVIOUSLY & GROWN  
OVER AGAIN - BALANCE OF UPPER FACE  
ROTTED.

NO TRACE FD. OF CEDAR TO S.E.  
COR. FALLS IN E. & W. FENCE  
LINE, 33 FT. WEST OF SMALL STREAM.  
(FITS CALL IN GOV'T FIELD NOTES)

AT COR. SET IRON PIPE WITH  
BRASS CAP MKD. "COUNTY SURVEYOR'S  
OFFICE 1963 T25S R6W  $\frac{1}{4}$   $\frac{S35}{S2}$   
T26S"

BLAZE & SCRIBE NEW TREES:

15" WHITE FIR N. 48 $\frac{1}{2}$ ° E 66 $\frac{1}{2}$  FT.  
MKD. " $\frac{1}{4}$  S35 CS BT"

9" DOUG. FIR S 58° W 78 $\frac{1}{2}$  FT.  
MKD. " $\frac{1}{4}$  S2 CS BT"

JUNE 27, 1963

M.G.

V.T.

M.D.

*Milo E. Godfrey*