

REN. T 25 S R^s 6 & 7 W $\frac{1}{4}$ S^s 13 & 18

FD, FIR TREE (NOW 37" DIAM.)

N 2° W 99° FT. - FAINT BARK SCRIB-
ING VISIBLE " $\frac{1}{4}$ " - TREE ALIVE &
STANDING - TOP PARTLY DEAD.

FD, FIR TREE (NOW 36" DIAM.)

N 82° E 42 $\frac{3}{4}$ - TREE RECENTLY
UPROOTED & DOWN - BARK SHOWS
EVIDENCE OF HAVING BEEN FACED
OFF WITH AXE - NO SCRIBING FD.

AT COR. SET IRON PIPE WITH
BRASS CAP MKD. "COUNTY SUR-
VEYOR'S OFFICE 1963 T 25 S
R 7 W $\frac{1}{4}$ S^s 13 & 18 R 6 W" - BUILD
MOUND OF STONE AROUND CAP.
BLAZE & SCRIBE 2 NEW TREES:

22" DOUG. FIR N 1° E 8 $\frac{2}{4}$ FT.
MKD. " $\frac{1}{4}$ S 18 CS BT"

15" DOUG. FIR S 85° W 20 $\frac{4}{4}$ FT.
MKD. " $\frac{1}{4}$ S 13 CS BT"

COR. LIES ON STEEP, ROCKY,
S.E. SLOPE, APPROX. 100 FT. SOUTH
OF TOP OF SPUR, AND BETWEEN
TWO LARGE OUTCROPS OF ROCK.

JULY 31, 1963

Phil E. Godfrey

M.G.
V.T.
M.S.

C.S. File No. 49/123⁰⁵