

RENEW  $\frac{1}{4}$  COR

10/11 TESS RSW

FOUND - BOTH OF TRAILS BTL 24" NW  
30" W DAK 34 1/2" E 100.3' S 100' S 10'  
FACE CENTER ROTTED. 20" NW 100"  
7/8" STAMP 385.0 78.5' I OPEN 100"  
WOOD SPLITTING 24" NORTH STAMP  
NOT FOUND. COR. IN OLD LOG ROAD.

SET BRASS CAP AT CORNER RAKO  
COUNTY SURVEYORS OFFICE 1960  
 $\frac{1}{4}$  S 10/11 TESS RSW

NEW BTL  
14" R. FIR BEAMS N 61 1/2° W 27.7'  
SCRIBED  $\frac{1}{4}$  S 10 C S 21'

15" R. FIR BEAMS N 84° E 18.6'  
SCRIBED  $\frac{1}{4}$  S 11 C S 21'

NOTE - COR 15 10' SOUTH OF  
E. W. FIELD

VAR 20'  $\frac{1}{4}$  C

APR 26-60  
13 1/2' W  
100'

DIETZEN NO. 395-6

C. S. File No. 49/124-5