

T25S R5W

COR.
SECS.7 | 8
18 | 17

RESET CORNER

RESET BRASS CAP SET IN 1960
WHICH HAD BEEN PULLED OUT, SET
CAP 1" BELOW GROUND SURFACE,

B.T.S AS CALLED FOR IN 1960
RENEWAL ALL IN GOOD CONDITION.

B.T.S:

18" W. OAK S65°W 140⁴/₄ FT.
(RESCRIBED IN 1960)

30" B. OAK N83°W 81⁵/₅ FT.
(EPPSTEIN'S RENEWAL)

14" LAUREL N58¹/₂°E 38⁵/₅ FT.
(SCRIBED IN 1960)

FEB. 23, 1962

Mils
E. Godfrey

M.G.
V.T.

+*0/

C. S. File No.

42/124-77