

Review $\frac{1}{4}$ 527/528 T255 R5W

Fd. O.B.T. 25 Follows

ORIG. 16" Now 34" Fir N34°W, 66° ft.

Now STUMP - SCRIBE visible - we open
higher to find scribe & Reverse. No

TRACE O.B.T. N.E. OR $\frac{5}{8}$ " I.P. Recorded
in Rev. #36. 2nd COR. point set

1" I.P. & BRASS CAP MKD. "COUNT 4

SURVEYOR'S OFFICE 1968 T255

$\frac{1}{4}$ 528/527 R5W" & M.K. New BT. -

20" D. Fir S 74° E, 112 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 527 CS BT" Note: BT. is on Top
of cut BANK of Log Landing - East of
COR. No other trees available.

Set 6 ft. Steel Fence post along
side BRASS CAP. COR. Lies on Very
steep West slope. Clearcut
all around except for seed trees to East.

August 20, 1968

V.R.T.
J.M.
V.P.

V.R. Tracy

O.K. J.W.L.

292

C.S. No. 22122-28