

REN. T 26 S R 5 W $\frac{1}{4}$ S $\frac{1}{16}$ S

FD. ROTTEN OAK STUMP S 55° W

193 1/2 FT. - BURL WOOD SHOWING REVERSE
OF OLD AXE MKS. FACES CORNER - SCAR
IS RIGHT SIZE, RIGHT SHAPE & IN RIGHT
POSITION FOR OLD B.T. BLAZE. I

BELIEVE IT TO BE OVERGROWTH OF OLD
B.T. BLAZE. - NO SCRIBING VISIBLE

A STUMP HOLE & ROTTEN LIMBS OF
OAK ON GROUND FIT APPROXIMATELY
LOCATION OF S.E. B.T.

CDR. LOCATION ALSO FITS 40 V'T
FIELD NOTES FOR CALL AT FOOT OF
HILL.

AT COR. SET IRON PIPE WITH BRASS
CAP MKD. "COUNTY SURVEYOR'S OFFICE
1964 T 26 S R 5 W $\frac{1}{4}$ S $\frac{1}{16}$ S" BUILD ROCK MOUND.

BLAZE & SCRIBE NEW TREES;
18" BLACK OAK S 6° E 51 1/2 FT.

MKD. "1/4 S 15 C S B T"

14" WHITE OAK S 65° E 111 1/2 FT.

MKD. "1/4 S 15 C S B T"

NO TREES CONVENIENT WEST OF
LINE.

FEB. 3, 1964

M.G.

W.S.

M.S.

Milo E. Godfrey

+ Q ✓

U.S. PHOTO 32/15 -21