

REN. T 26 S R 4 W COR. 20 | 21  
SECS. 29 | 28

FD. IRON PIPE WITH BRASS

CAP SET BY RICHARDSON IN 1947.

PIPE WAS BENT OVER & CAP MASHED  
INTO GROUND.

FD. WHITE OAK (NOW 12" DIAM.)

S 31 $\frac{1}{4}$ ° E 32 $\frac{1}{2}$  FT. SHOWS 2 GOOD AXE  
SCARS. - DID NOT CUT OPEN.

FD. WHITE OAK (NOW 28" DIAM.)

N 37 $\frac{1}{2}$ ° E 49 $\frac{1}{2}$  FT. - (ORIG. B.T.). SHOWS

FAINT TRACES OF SCRIBING, STILL VISIBLE  
ON BADLY ROTTED OLD FACE.

THE OTHER 3 B.T.'S MKD. IN 1947  
HAVE ALL BEEN BULDOZED OUT, BUT  
STUMP HOLES & PIECES OF OAK ROOTS  
REMAIN.

STRAIGHTEN & RESET CAP IN ITS  
ORIG. LOCATION. DRIVE STEEL FENCE  
POST ALONGSIDE,

BLAZE & SCRIBE 3 NEW TREES:

11" WHITE OAK N 18° W 42 $\frac{1}{2}$  FT.

MKD. "T 26 S R 4 W S 20 CS BT"

7" WHITE OAK N 55° E 46 $\frac{1}{2}$  FT.

MKD. "T 26 S R 4 W S 21 CS BT"

20" DOUGLAS FIR S 10° W 70 $\frac{1}{2}$  FT.

MKD. "T 26 S R 4 W S 29 CS BT"

COR. LIES 25 FT. SOUTH OF AN E.W.  
FENCE LINE.

M.G.

V.T.

M.S.

J.C.S. File No. 19/125-105



FRED.

... YOU PROBABLY REMEMBER THIS  
COR. REPORTED BULDOZED OUT BY  
W.M. <sup>Idleyd Box 295, Robing</sup>  
BUD UPDEGRAVE IN DIGGING FIRE  
TRAIL.

THE PIPE & CAP WERE STILL  
THERE, BUT BENT OVER & MASHED  
INTO THE GROUND.

I RESET CAP, & DROVE STEEL  
FENCE POST ALONGSIDE.

ONLY ONE B, T, MKD. IN 1947  
WAS STILL STANDING, - ALL THE  
REST WERE DUG OUT,  
MKD. 3 NEW TREES,

---

USED STEEL FENCE POST

\$ .98

3 MAN CREW 1/2 DAY. —

50.00

---

FD

**m & m**

**PRINTERS - LITHOGRAPHERS**

**242 S. E. JACKSON STREET**

**TELEPHONE OR 3-8591**

The owners  
held responsible by you when  
contracting fire trail. The  
County feels you are responsible  
for re-setting burner.