

RENEW MC RT BANK 10/11 T265 R5W

FOUND - ORIG. 19" NOW 29" W. OAK
N 25° 10' W 126.6' I OPEN & FIND GOOD
SCRIBING "BT" 5/0". ORIG. 12" NOW
29" W. OAK N 16° E 192.1' SHOWS
GOOD SCAR. I DO NOT OPEN.

NOTE - COR. IN RIVER SET WITH COR.

SET BRASS CAP AT WIT COR. MARK
WIT COR. 185' SOUTH TO MC SIOCK
T265 R5W COUNTY SURVEYORS OFFICE
1958

NEW BTS -

29" W. OAK (ORIG. N E BT FOR MC)
EAST 53.5' SCRIBED W MC SIOCK BT
7" W. OAK BEARS S 62° W 3.8'
SCRIBED W MC SIOCK BT

RENEW 1/4 COR. 10/11 T265 R5W

FOUND - ORIG. 20" NOW 48" B. OAK
N 0° W 456.1' I OPEN & FIND GOOD
SCRIBING "BT" I FIND NO TRACE OF
ORIG. N E BT

SET BRASS CAP AT CORNER MARK
1/4 SIOCK T265 R5W COUNTY
SURVEYORS OFFICE 1958

NEW BTS

6" W. OAK BEARS N 74° W 249'
SCRIBED 1/4 SIOCK BT

13" B. OAK BEARS S 80° E 307'
SCRIBED 1/4 SIOCK BT

DIETZEN NO. 385-6

✓

C.S. File No. 19/128-9