

RENEW  $\frac{1}{4}$  COR. 26/25 T26S R7W

FOUND 12" FIRS SCRIBED BY HESTOR 25.94/99  
1951 NOW DEAD. I ALSO FIND  $\frac{5}{8}$ " 11" B.  
3" UNDER SURFACE AT CORNER. I ALSO  
FIND 28" OAK STUMP THAT CHECKS  
BEARING & DIST. 502' ORIG. SW BT I OPEN  
NEAR BASE BUT DO NOT FIND SCRIBING.

NEW BT.

12" W OAK BEARS N 12° E 76.2'  
SCRIBED  $\frac{1}{4}$  S 25 CS BT

SET 1" X 24" I. PIPE 180' SOUTH OF  
 $\frac{1}{4}$  COR. FOR REF. POINT

RENEW  $\frac{1}{4}$  COR. 25/36 T26S R7W

FOUND ORIG. 20" NOW 32" B. OAK  
SNAG N 17° E 51.2' HOPEN & FIND  
GOOD SCRIBING BT. ORIG. 10' NOW REMAINS  
ONLY OF SW BT. I FIND GOOD SCRIBING  
BT ON SECT. NEAR FENCE CHECKS  
BEARING & DIST. TO OLD STUMP HOLE.

SET BRASS CAP AT COR. MND COUNTY  
SURVEYORS OFFICE 1959  $\frac{1}{4}$  S 25 T26S  
R7W.

NEW BT.

8" LAUREL BEARS N 53° W 260'  
SCRIBED  $\frac{1}{4}$  S 25 CS BT

7" R. FIR BEARS S 65° E 18.5'  
SCRIBED  $\frac{1}{4}$  S 36 CS BT.

NOTE. THIS BT IN E. W. FENCE LINE

VAR 20 1/2

JAN 9 - 59  
J. P.  
M. G.  
S. G.

C. S. File No. 49/129