

RENEW  $\frac{1}{4}$  COR. 16/15 T27S R4W

FOUND - BOTH ORIG. BTS. ORIG. 16" NOW 24" DOWN OAK. S 76° W 19.1' I OPEN & FIND GOOD SCRIBING BT ORIG. 10" NOW 24" B. OAK N 25° E 11.9' SHOWS SCAR I DONOT OPEN THIS BT THUS

~~BT USED FOR~~  
~~TRANCE COR.~~

SET BRASS CAP AT CORNER MKD COUNTY SURVEYORS OFFICE 1958  
 $\frac{1}{4}$  S 16/15 T27S R4W

NEW BTS.

20" R. FIR BEARS S 76° W 18.0' SCRIBED  $\frac{1}{4}$  S 16 CS BT

23" R. FIR BEARS S 76° E 13.0' SCRIBED  $\frac{1}{4}$  S 15 CS BT

RENEW  $\frac{1}{4}$  COR.  $\frac{16}{21}$  T27S R4W

FOUND - ORIG. 10" NOW 24" B. OAK N 40° E 13.2' SHOWS TWO GOOD SCARS MAY HAVE CENTER ROTTED I DO OPEN. I ALSO FIND BOTH BTS AS RENEW 1908 I OPEN NEXT & FIND GOOD SCRIBING.

SET BRASS CAP AT CORNER MKD COUNTY SURVEYORS OFFICE 1958  
 $\frac{1}{4}$  S 16 T27S R4W  
 $\frac{1}{4}$  S 21

NEW BTS.

8" B. OAK BEARS N 80° E 28.2' SCRIBED  $\frac{1}{4}$  S 16 CS BT

26" R. FIR BEARS S 25° W 2.4' SCRIBED  $\frac{1}{4}$  S 21 CS BT

DEC 30-58  
J. B.  
M. G.  
S. B.

VAR 20  $\frac{1}{2}$

✓ C. S. File No. 49/30.1

DIETZGEN NO. 385-6