

RENEW $\frac{1}{4}$ COR. 32 - 275 RAW

27

FOUND - BOTH B.T.S AS RECORDED BY ROBERTS 1904. 30" NOW 36" FIR SNAG SHOWS GOOD BARK SCRIBING $\frac{1}{4}$ S C S BT. N 72° W 317. 8" NOW 28" FIR S 42° E 242. 2" SHOWS OLD FACE I DO NOT OPEN

NOTE - COR. T&US

I ALSO FIND AUTO AXLE AT COR. STUMP OF BT AS RECORDED BY B.B.J. BARK SCRIBED "BT".

NEW B.T.S.

6" R. FIR BEARS N 36° E 140' SCRIBED $\frac{1}{4}$ S 27 C S BT

20" R. FIR S 40° E 342' RECORDED $\frac{1}{4}$ S 27 C S BT

RENEW $\frac{2}{4}$ T 275 RAW

27

FOUND - AUTO AXLE AT COR. 24" NOW 30' B.O. STUMP PARTLY ROTTED NO SCRIBING FOUND.

18" NOW 22' W. OAK S 15° W 1356' SHOWS GOOD SCAR I DO NOT OPEN. 18" NOW 28" B.OAK N 75° E 730' I DO NOT OPEN I FIND NO TRACE OF N 49° E BT.

NOTE - FENCE COR. BEARS N 70° W 890'

NEW B.T.S.

9" R. FIR BEARS N 51° E 256' SCRIBED S 22 - 275 RAW C S BT

5" R. FIR BEARS N 47° W 70.5' SCRIBED $\frac{1}{4}$ R 1 T 275 RAW C S B.T

DIETZEN NO. 385-6

Dec 1958

LC. S. File No. 49/130-4