

RENEW $\frac{1}{4}$ COR. $\frac{1}{12}$ T32S R3W

FOUND - ORIG. 7" NAW 9" FIR SNAG
S 36° W 6.6' PREVIOUSLY OPENED SHOWS
GOOD SCRIBING $\frac{1}{4}$ S 12 ORIG. NE BT WOULD
BE UNDER ROAD FILL.

NOTE - CORNER STONE WOULD BE UNDER
6' I ROAD FILL I DO NOT SEARCH FOR IT I
FIND 3" WRL WITH STAKE MKD. $\frac{1}{4}$ COR. WHICH
BEARS N 57° E 6.2' FROM BRASS CAP.

SET BRASS CAP AT CORNER MKD
COUNTY SURVEYORS OFFICE IS 59
 $\frac{1}{4}$ S 12 T32S R3W

NEW B.T.S.

16" R. FIR BEARS N 85 $\frac{1}{2}$ ° E 42.7'
SCRIBED $\frac{1}{4}$ S 12 CS BT

17" R. FIR BEARS S 50° E 93.6'
SCRIBED $\frac{1}{4}$ S 12 CS BT

VAR 20 $\frac{1}{2}$ °

FEB. 11 - 59
L. B.
M. G.
G. B.

DIETZEN NO. 385-6

FILED
RECEIVED

FEB 24 1959

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

✓ C. S. File No. 49/136'