

RENEW $\frac{25}{36} \frac{30}{31}$

T 295

R/W R/W

FOUND - ORIG 10" NW 8" LAUREL SNAG
SHOWS GOOD SCRIBING "S 3 T 295 BT"
N 33° E 238'. I ALSO FIND ORIG.
S W BT DOWN DOZED OUT OF POSITION
SHOWS GOOD SCRIBING "S 36 T 295"
I FIND ALBTS AS RECORDED BY
BOYER EXCEPT NE BT WHICH IS NOW
A SNAG. NO OTHER TREES NEAR TO US

SET BRASS CAP AT CORNER 2
ALONGSIDE SQUARED & SCRIBED COR.
DOT MARKED BRASS CAP COUNTY
SURVEYORS OFFICE 1954.

$\frac{25}{36} \frac{30}{31}$

T 295

$\frac{30}{31} \frac{30}{31}$

R/W R/W

NO NEW TREES SCRIBED

RENEW $\frac{1}{4}$ COR 36 | 31 T 295
R/W R/W

FOUND - 1" PIPE AT COR. & BOTH
ORIG. B.T.S. I ALSO FIND STONE AT
COR. CHISELED $\frac{1}{4}$ ORIG. S W BT NOW

STUMP SHOWS GOOD SCAR ORIG SE BT
NOW DEAD SHOWS GOOD SCRIBING "BT"

NEW B.T.S.

20" R FIR BEARS S 11° E 50'
SCRIBED S 31 $\frac{1}{4}$ S BT

8" W FIR BEARS N 53° W 44'
SCRIBED $\frac{1}{4}$ S 36 C S BT

APRIL 27 59

J. BYRAN
S. BILOW

C. S. File No. 19/1399-2

DIETZGEN N. O. 3885-6