

RENEWED $\frac{1}{4}$ COR. 16 | 15 T 28 S R 6 W

FOUND - $1\frac{1}{4}$ " I.P. NEAR TOP OF BANK ON EAST SIDE OF DRAINAGE DITCH FROM WHICH TOP OF 30" CONC. PIPE IN EAST WEST DITCH BEARS SP2 W 20 S' No TREES NEAR FOR BT.

RENEW $\frac{1615}{2122}$ T 28 S R 6 W

FOUND - $\frac{1}{2}$ " I.P. AT COR. & BT AS RECORDED BY BYRON 1959.

SET BRASS CAP ALONGSIDE I.P. & MARK COUNTY SURVEYORS OFFICE 1962 $\frac{516}{521}$ | $\frac{515}{522}$ T 28 S R 6 W

NEW BT.

9" W. OAK BEARS 53 S 9' E 56 S
SCRIBED 322 T 28 S R 6 W C 5 BT

ROYEVILLE V. A. B.

JAN 17 - 62
BYRON
I.P.

C. S. File No.

49 | 139-25

DIETZEN NO. 385-6