

RENEW $\frac{1}{4}$ COR. 5 T 29S R6W

FOUND - BOTH BITS AS RECORDED BY BOYER 1981. THE NE BIT IS NOW DOWN SHOWS GOOD BARK FACES BUT IT DON'T FIND SCRIBING THE BIT IS NEW STUMP SHOWS FAINT SCRIBE MARK ON BARK THIS AREA HAS BEEN LOGGED & BURNED.

COR. IS AT ~~THE~~ CORNER CUR. WE DO NOT FIND I.P. SET FOR COR. BY BOYER.

SET BRASS CAP AT CORNER MKD COUNTY SURVEYORS OFFICE 1982

$\frac{1}{4}$ SS T 29S R6W

NEW BIT

7" LAUREL BEARS N 65° W 1' 5" SCRIBED $\frac{1}{4}$ S T C S BIT

NO TREES NEAR TO SOUTH

APR 11 1982
J.B.
D.M.
G.P.

RENEW $\frac{15}{21}$ T 29S R6W

FOUND - AXLE AT COR. ALL BITS AS RECORDED BY B.B.T. 15' 1" EXCEPT ALL BEARING TO BITS. I FOUND AS BEING NOW 18" FIR BEARS 527° W NOT 537° W NOW 18" FIR BEARS 519° W NOT 510° W NOW 20" FIR STUMP N 105° W NOT N 87° W STUMP SHOWS GOOD BARK SCRIBING "BT" NOW 12" W.O. BEARS N 95° E NOT N 55° E ALL DISTANCES ARE OK AS RECORDED

NEW BIT

6" W. OAK BEARS N $3\frac{1}{2}^{\circ}$ W 1' 2" SCRIBED $\frac{1}{4}$ S T C S BIT

DIETZGEN NO. 385-6