

RENEW <sup>2912</sup> 29/28 T295 R6W

FOUND - PIPE AT COR. # 15' R.E.R.

389° W 155' GOOD CONDITION

ALSO N.E. BT IS OK. LAUREL

TO SW NOW BEAD AND FIR TO

SE NOW SNAG. F'LD

VED

APR 10 1962

NEW BT.

R. FIR BEARS 592' E 98.2' VEYOR

SCRIBED 528 T295 R6W CSBT

\* \* ✓  
9" R. FIR BEARS N 31° W 65'  
SCRIBED 520 CS BT

RENEW  $\frac{1}{4}$  COR.  $\frac{21}{28}$

FOUND - 1" I.P. AT CORNER # 2' SOUTH  
OF E W FENCE. 36" LAUREL 529° E W 368'  
SHOWS GOOD SCRIBING. COLE'S 14" FIR  
N 12' W 110' NOW STUMP.

NEW BT.

9" R. FIR N 14° W 40.8'

SCRIBED  $\frac{1}{4}$  S 21 CS BT

\* \* ✓

CS 49 | 139-39