

RENEW $\frac{1}{4}$ 33/35 T295 R7W

FOUND - BRASS CAP AT CORNER
1924 N.W. BT PARTLY ROTTED FACE
BURIED. WE DO NOT FIND A N.E. BT
ORIG. N.E. BT SHOWS OLD SEARS
CENTER ROTTED.

NEW B.T.S.

94' R. FIR BEARDS S 45° E 11.3'
SCRIBED $\frac{1}{4}$ 33/35 N.E. BT

81' R. FIR BEARDS S 56° W 10.2'
SCRIBED $\frac{1}{4}$ 33/35 S.W. BT

U. B.
D. B.
U. B.

MAY 15-62

VAR 20 $\frac{1}{2}$ °

DIETZEN NO. 385-6

FILED

RECEIVED

MAY 15 1962

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

+ * O V

C. S. File No. 49/139-59